SQUIRE, SANDERS & DEMPSEY L.L.P.

1300 Huntington Center 41 South High Street Columbus, Ohio 43215-6197

Office: +1.614.365.2700, Fax: +1.614.365.2499



jdemonte@ssd.com 614-365-2809

May 12, 2006

SQUIRE

VIA FEDERAL EXPRESS

Elise S. Feldman
U.S. Department of Justice
Environmental Enforcement Section
Environmental and Natural Resources Division
601 D Street, Mailroom 2121
Washington DC 20004

Re: EaglePicher Holdings, Inc., et al., No. 05-12601 (Bankr. S.D. Ohio)

Dear Elise:

Please find enclosed several documents that we are providing to our consultant, ENVIRON. Because we are providing these documents to ENVIRON, we are producing copies to you as a courtesy. They are Bates numbered OH001222 to OH001251. The enclosed documents are publicly available documents that were provided to us in response to an information request to the Shelby County Board of Health regarding the Sidney, Ohio site. By copy of this letter, we are also providing a copy of these documents to Jack McManus of the Ohio Attorney General's office.

If you have questions regarding the foregoing, please do not hesitate to let us know.

Very truly yours,

/s/ Jessica E. DeMonte

Jessica E. DeMonte

Enclosure

Elise S. Feldman May 12, 2006 Page 2

cc: Jon Gulch (via Fed Ex)

Jack McManus (Ohio, via Fed Ex)

Jason Barbeau (via Fed Ex)
Stephen D. Lerner (via email)
Scott A. Kane (via email)
Karen A. Winters (via email)
Patrick J. Brooks (via email)

JED/acp

U.S. ENVIRONMENTAL PROTECTION AGENCY

MAY 17 2006

OFFICE OF REGIONAL COUNSEL



Ross Aluminum Foundries

P.O. Box 609 Sidney, Ohio 45365-0609

937/492-4134 Fax 937/498-1883

February 22, 2000

Robert Mai, RS Sidney-Shelby Cnty B of H 202 West Poplar St. Sidney, Ohio 45365

RE: Sand Monofill at Brooklyn Avenue



Dear Mr. Mai:

The following analysis summary for spent foundry sand is being submitted for your review.

Samples were collected by Swank Consulting, Inc., and represent the foundry sand deposited on the Ross Aluminum Foundries, Division of Eagle Picher Ind. property located west of Brooklyn Avenue.

	•			
1-28-99	TOTAL PH		0.12 mg/l	
7-26-99	TOTAL PH	ENOLICS		N/D
11-11-99	Acidity - Total	8.79 S.U.	8.16 S.U.	8.10 S.U.
	Alkalinity	40.5	29.1	22.8
	Conductivity	196 mmhos	236	7.40
	pН	7.57 S.U.	7.50 S.U.	7.4 S.U.
	Sulfate	1269 mg/kg	1510	1186
	TDS	221 mg/kg	85	144
	Aluminum	9865 mg/kg	4305	2435
	Iron	11647 mg/kg	20721	15055
	Manganese	90.5 mg/kg	165	124
	Vanadium	4.92 mg/kg	4.70	3.66
	Zinc	91.5 mg/kg	52.6	22.0
1-22-00	Cyanide			N/D
	Fluoride			0.80 mg/l

Phenolics	0.1 mg/l
Arsenic	N/D
Barium	0.29 mg/l
Cadmium	N/D
Chromium	N/D
Lead	N/D
Mercury	N/D
Selenium	N/D
Silver	N/D

On January 28, 2000 Ross Aluminum was sold by Eagle Picher Ind., Inc. The Brooklyn property was not sold and remains an asset of Eagle Picher Ind., Inc. As of 1-28-2000 Ross Aluminum stopped sending spent foundry sand to this property. It is my understanding that Eagle Picher Ind. will be re-grading and capping the area with top soil to close its use as a monofill.

If you have any questions on any of this information please let me know.

Sincerely

Ted Settlage

Coord. Env. & Safety




Ross Aluminum Foundries

P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

February, 3 1999

Joe E. Sargeant, R.S. Director Of Environmental Health Sidney-Shelby County board Of Health 202 West Poplar Street Sidney, OH 45365



Dear Mr. Sargeant:

The following analysis summary for spent foundry sand is being submitted for your review.

Samples were collected by Swank Consulting, Inc., and analyzed by Brookside Laboratories, Inc., and represent the foundry sand deposited on the Ross Aluminum Foundries property located west of Brooklyn Avenue.

3-12-98	TCLP For Phenolics	2.03 mg/l
12-28-98	TCLP For Metals Arsenic Barium Cadmium Chromium Cyanide (total)	N/D 0.05 mg/l N/D 0.04 mg/l N/D
	Fluoride Lead Mercury Phenolics Selenium Silver	2.0 mg/l N/D N/D 0.05 mg/l N/D N/D

If you have any questions or require additional information please let me know.

Sincerely,

Ted Settlage


Coordinator Environ. & Safety

EAGLE PICHER



Ross Aluminum Foundries

P.O. Box 609 Sidney, Ohio 45365-0609 937/492-4134 Fax 937/498-1883



Joe E. Sargeant, R.S. Director Of Environmental Health Sidney-Shelby County board Of Health 202 West Poplar Street Sidney, OH 45365

Dear Mr. Sargeant:

The following analysis summary for spent foundry sand is being submitted for your review.

Samples were collected by Swank Consulting, Inc., and analyzed by Brookside Laboratories, Inc., and represent the foundry sand deposited on the Ross Aluminum Foundries property located west of Brooklyn Avenue.

10.00.00	not allerto	at all be		
12-30-96	TCLP For Pl	henolics 10,3mgl	0.09 mg/i	
	Total	Cyanide 0.2	N/D	
		Cyanide 2.2 mg/f	0.09 mg/l	
		Arsenic	0.00067 mg/l	
		Barium	N/D	
		Chromium	0.32	
		Lead	N/D	
		Mercury	N/D	
		Selenium	N/D	
		Silver	0.10 mg/l	
2-8-97	TCLP For Ph	nenolics	0.09 mg/l	
8-7-97	TCLP For Ph	nenolics	0.16	
			0.16 mg/l	



12-31-97	TCLP For Pheno	olics	0.09 mg/l
	Total Cy	anide	N/D
	Fli	uoride	1.12 mg/l
	Ar	senic	0.0014 mg/l
	Ва	ırium	0.36 mg/l
	Ca	dmium	N/D
	Ch	romium	N/D
	Le	ad	N/D
	Me	ercury	N/D
	Se	lenium	N/D
	Sil	ver	0.10 mg/l

If you have any questions or require additional information please let me know.

Sincerely,

Ted Settlage
Coordinator Environ. & Safety



Ross Aluminum Foundries P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

January 9, 1997

JAN 10 1937

SIDWERSONIES TO SOMY MARKET

Joe E. Sargeant, R.S.
Director Of Environmental Health
Sidney-Shelby County Board Of Health
202 West Poplar Street
Sidney, OH 45365

Dear Mr. Sargeant:

The following analysis summary for spent foundry sand is being submitted for your review.

Samples were collected by Swank Consulting, Inc. and analyzed by Brookside Laboratories, Inc. and represent the foundry sand deposited on the Ross Aluminum Foundries property located west of Brooklyn Avenue.

DATE	TOTAL PHENOLICS	TCLP FOR PHENOLICS
02-01-96	54.0 mgikg	
02-28-96	13.6 mg/kg	
03-29-96	16.2 mglkg	
07-31-96	12.2 mglkg	
08-29-96	54.0 mglkg	
10-10-96		0.29 mglkg
12-19-96		0.96 malka

10-10-96 and 12-19-96 samples were analyzed using EPA 420.1 TCLP water extraction method, as established by Ohio EPA policy for disposal of non-toxic fly ash, bottom ash, and foundry sand.

If you have any questions or require additional information please let me know.

Sincerely,

Ted Settlage

Coordinator Env. & Safety

010997.TAS





Ross Aluminum Foundries

P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

January 18, 1996

RECEIVED

JAN 22 1996

SIDNEY-SHELBY COUNTY HEALTH DEPT

Joe E. Sargeant, R.S.
Director Of Environmental Health
Sidney-Shelby County Board Of Health
202 W. Poplar St.
Sidney, OH 45365

Dear Mr. Sargeant:

The following analysis summary for spent foundry sand is being submitted for your review.

Samples were collected by Swank Consulting, Inc. and analyzed by Brookside Laboratories, Inc. and represent the foundry sand deposited on Ross property west of Brooklyn Avenue and located between Fielding Road and Ardiss.

DATE TOTAL PHENO			
2-22-95	` 10.7 mg/kg		
4-27-95	31.5 mg/kg		
5-12-95	53.2 mg/kg		
7-10-95	9.63 mg/kg		
8-29-95	13.3 mg/kg		
9-21-95	25.0 mg/kg		
11-30-95	21.8 mg/kg		

If any additional information is required please let me know.

Sincerely,

T. A. Settlage

Coord. Environ. & Safety

011896.TS





Ross Aluminum Foundries P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

January 13,1995

Hiller

JAN 17 1995

SIDNEY-SHELLEY COUNTY

Joe E. Sargeant, R.S. Director Of Environmental Health Sidney-Shelby County Board Of Health 202 W. Poplar St. Sidney, OH 45365

Dear Mr. Sargeant:

Please find attached analysis for spent foundry sand in accordance with your request of January 24, 1990.

Samples were collected by Monte Swank, EID representative for Brookside Farms Laboratory Assn. and owner of Swank Consulting. Sampling is representative of sand deposited on Ross property west of Brooklyn Avenue and located between Fielding Road and Ardiss.

Sincerely,

ROSS ALUMINUM FOUNDRIES

James F. Rinker

Environmental Manager

011395.jfr



BROOKSIDE LABORATORIES, INC.

ENVIRONMENTAL & INDUSTRIAL DIVISION
P.O. BOX 456 308 S. MAIN STREET
NEW KNOXVILLE, OH 45871

(419) 753-2448

ANALYSIS REPORT

We are pleased to submit the following Analysis Report. Please review the data and feel free to call us if you have questions or need additional tests and/or technical assistance.

GENE	RAT	INEC	WW.	TION
OWIL		THE PARTY	7.443.19	

Account No: 60243

Report Submitted To: Jim Rinker

Client Name: Ross Aluminum Foundries

Report No: |\$49313

Project Name:

Report Date: 01/10/95

Site Name/Location:

Sample Collected By: Swank Cons., inc.

Comments:

ANALYTICAL RESULTS

Analytical results are presented on page 2 through page 5 of this report.

Jefrey Brachok

Lam V. Ho, Ph.D., REP,
Division Coordinator

Director, EID

Brookside Laboratories, Inc.

PAGE NO: 2

REVIEWER INITIALS:

DATE SAMPLED: 12/27/94

DATE RECEIVED:12/28/94

REPORT NUMBER: 1549313

TEST NAME: ** GENERAL ANALYSIS **

SAMPLE MATRIX: SOLID

CIJENT NAME: Ross Aluminum Foundries

FILE NO: **60243**

PROJECT NAME:

SAMPLE ID:

SAMPLE DESCRIPTION: CORE SAND MATERIAL

LAB NUMBER: 1S49313

MDI	TOTAL STATE OF THE	0.03 mg/kg
RESTIT	•	14.4 mg/kg
ANALYST		LLR
DATE	ANALYZED	01/06/95
REPARATION ANALYTICAL	METHOD	EPA 420.1
PREPARATION	METHOD	
ANALYTE		TOTAL PHENOLICS
ZOO.		A850

CLIENT NAME: Ross Aluminum Foundries

PROJECT NAME :

PAGE NO: 3

REPORT NUMBER: 1S49313

REVIEWER INITIALS:

4

TEST NAME: ** TCLP Metals **

SAMPLE MATRIX: TCLP EXTRACT

DATE SAMPLED: 12/27/94

SAMPLE ID: BROOKLYN

DATE RECEIVED: 12/28/94

SAMPLE DESCRIPTION: LANDFILL MATERIAL

DATE EXTRACTED: 12/30/94

LAB NUMBER: 1849314

DATE ANALYZED: 01/09/95

EXTRACTION METHOD NO: EPA 1311

ANALYST: JAS

EPA HW NO*	ANALYTE	METHOD	RESULT (mg/l	REGULATORY) LIMIT (mg/l) MDL (mg/l
D 004	ARSENIC	EPA 7061	N/D	5.0	0.00002
D005	BARIUM	EPA 6010 A	0.31	100.0	0.05
D006	CADMIUM	EPA 6010 A	0.034	1.0	0.003
D007	CHROMIUM	EPA 6010 A	0.40	5.0	0.03
D008	LEAD	EPA 6010 A	0.08	5.0	0.05
D 009	MERCURY	EPA 7470	N/D	0.2	0.0002
D 01 0	SELENIUM	EPA 7741	N/D	1.0	0.00006
D 01 1	SILVER	EPA 7760	0.51	5.0	0.005

^{*} EPA's Hazardous Waste Number

^{**} N/D - None Detected

CLIENT NAME: Ross Aluminum Foundries

PROJECT NAME:

PAGE NO: 4

REPORT NUMBER: |\$49313

REVIEWER INITIALS:

TEST NAME: ** TCLP Volatile Organic Compounds **

SAMPLE MATRIX: TCLP EXTRACT

DATE SAMPLED: 12/27/94

SAMPLE ID : BROOKLYN

DATE RECEIVED: 12/28/94

SAMPLE DESCRIPTION: LANDFILL MATERIAL

DATE EXTRACTED: 01/03/95

LAB NUMBER: 1849314

DATE ANALYZED: 01/06/95

EXTRACTION METHOD NO: EPA 1311

ANALYST: PAS/CJH

EPA HW NO*	ANALYTE	METHOD	RESULT (mg/l)	REGULATORY LIMIT (mg/l)	MDL (mg/l)
D018	BENZENE	EPA 8020	N/D	0.5	0.0002
D019	CARBON TETRACHLORIDE	EPA 8010	N/D	0.5	0.00012
D021	CHLOROBENZENE	EPA 8010	N/D	100	0.0002
D022	CHLOROFORM	EPA 8010	N/D	6.0	0.00005
D027	1,4-DICHLOROBENZENE	EPA 8010	N/D	7.5	0.00024
D028	1,2-DICHLOROETHANE	EPA 8010	N/D	0.5	0.00003
D029	1,1-DICHLOROETHYLENE	EPA 8010	N/D	0.7	0.00013
D035	METHYL ETHYL KETONE	EPA 8015	N/D	200	0.015
D039	TETRACHLOROETHYLENE	EPA 8010	N/D	0.7	0.00003
D040	TRICHLOROETHYLENE	EPA 8010	N/D	0.5	0.00012
D043	VINYL CHLORIDE	EPA 8010	N/D	0.2	0.00018

^{*} EPA's Hazardous Waste Number

^{**} N/D - None Detected

CLIENT NAME: Ross Aluminum Foundries

PROJECT NAME:

PAGE NO: 5

REPORT NUMBER: IS49313

REVIEWER INITIALS:

TEST NAME: ** TCLP Semi-Volatile Organic Compounds **

SAMPLE MATRIX: TCLP EXTRACT

DATE SAMPLED: 12/27/94

SAMPLE ID: BROOKLYN

DATE RECEIVED: 12/28/94

SAMPLE DESCRIPTION: LANDFILL MATERIAL

DATE EXTRACTED: 12/30/94

LAB NUMBER: 1849314

DATE ANALYZED: 01/06/95

EXTRACTION METHOD NO: EPA 1311/3510

ANALYST: PAS/MCW

EPA HW N	1	METHOD	RESULT (mg/l)	REGULATORY LIMIT (mg/i)	MDL (mg/l)
D023	O-CRESOL	EPA 8270	0.036	200	0.010
D024	M&P-CRESOL	EPA 8270	N/D	200	0.010
D026	CRESOL (TOTAL)	EPA 8270	0.036	200	0.010
) D030	2,4-DINITROTOLUENE	EPA 8270	N/D	0.13	0.010
D032	HEXACHLOROBENZENE	EPA 8270	N/D	0.13	0.010
D033	HEXACHLOROBUTADIENE	EPA 8270	N/D	0.5	0.010
D034	HEXACHLOROETHANE	EPA 8270	N/D	3.0	0.010
D036	NITROBENZENE	EPA 8270	N/D	2.0	0.010
D037	PENTACHLOROPHENOL	EPA 8270	N/D	100	0.050
D038	PYRIDINE	EPA 8270	N/D	5.0	0.500
D041	2,4,5-TRICHLOROPHENOL	EPA 8270	N/D	400	0.010
D042	2,4,6-TRICHLOROPHENOL	EPA 8270	N/D	2.0	0.010

^{*} EPA's Hazardous Waste Number

^{)**} N/D - None Detected





JAN 03 1994 DNEY-SHELBY COUNTY

BROOKSIDE LABORATORIES, INC.

ENVIRONMENTAL & INDUSTRIAL DIVISION
P.O. BOX 456 308 S. MAIN STREET
NEW KNOXVILLE, OH 45871

(419) 753-2448

ANALYSIS REPORT

We are pleased to submit the following Analysis Report. Please review the data and feel free to call us if you have questions or need additional tests and/or technical assistance.

GENERAL INFORMATION		
Account No.: 60243	_ Report Submitted	To: <u>Jim Rinker</u>
Client Name: Ross Aluminum Foundries	Report No.:	
Project Name:	Report Date:	12/23/93
Site Name/Location: Sample Collected By: Swank Cons., Inc.	.	0 CC 1203
ANALYTICAL RESULTS		E 2026 02.60
Analytical results are presented on page 2 th	nrough page 4	of this report.
AUTHORIZED) SIGNATURES	
Peter A. Condaris QA/QC Officer	Lam V. Ho, I Director, Ell	

PAGE NO: 0002
REPORT NO: 1539704

REVIEWER INITIALS:

TEST NAME: ** TCLP METALS **

SAMPLE MATRIX: TCLP Extract

DATE SAMPLED : 12/12/93

SAMPLE ID:

DATE RECEIVED: 12/13/93

SAMPLE DESCRIPTION: LANDFILL SAMPLE

LAB NUMBER: IS39704

DATE EXTRACTED: 12/13/93

EXTRACTION METHOD NO: EPA 1311

DATE ANALYZED: 12/22/93

ANALYST: JAS

EPA HW NO*	ANALYTE	METHOD	RESULT(mg/1)	REQULATORY LIMIT (mg/l)	MDL (mg/l)
D004	Arsenic	EPA 7061	0.00048	5.0	0.00004
0005	Barium	EPA 6010	A 1.16	100.0	0.10
0006	Cadmi um	EPA 6010	A 0.21	1.0	0.005
0007	Chromium	EPA 6010	A 0.07	5.0	0.05
8000	Lead	EPA 6010	A 1.84	5.0	0.10
1009	Mercury	EPA 7470	n/d	0.2	0.0002
0010	Selenium	EPA 7741	0.00019	1.0	0.00012
0011	Silver	EPA 7760	0.13	5.0	0.01

^{*} N/D - None Detected



^{*} EPA's Hazardous Waste Number

·
_
=
•
m
*
œ
.=
_
\sim
~
=
Œ
=
_
u
\sim
**
Laboratories
_
_
_
_
_
_
_
_
_
_
_
_
_
_
_
okside
_

PAGE NO: 0003 REPORT NO: 1839704

REVIEWER INITIALS:

DATE SAMPLED: 12/12/93

DATE RECEIVED: 12/13/93

TEST NAME: ** GENERAL ANALYSIS **

SAMPLE MATRIX: SOLID

SAMPLE ID:

SAMPLE DESCRIPTION: LANDFILL SAMPLE

LAB NUMBER: 1839704

	0.02 mg/l 0.20 mg/l 0.03 mg/l
MOL	0.02
RESULT	N/D 0.60 mg/1 N/D
ANALYST	LLR
DATE ANAL	12/21/93 12/17/93 12/17/93
ANAL METHOD DATE ANAL ANALYST	EPA 335.2 EPA 340.2 EPA 420.1
PREP METHOD	
ANALYTE	CYANIDE - TOTAL FLUORIDE TOTAL PHENOLICS
CODE	IA240 IA360 IA850

* N/D - None Detected



Brookside Laboratories, Inc.

FILE NO: 60243

PAGE NO: 0004 REPORT NO: 1839704

DATE SAMPLED : 12/12/93

DATE RECEIVED: 12/13/93

REVIEWER INITIALS:

** GENERAL ANALYSIS ** TEST NAME:

SAMPLE MATRIX: WASTEWATER

SAMPLE ID:

SAMPLE DESCRIPTION: LANDFILL SAMPLE

UB39705 LAB NUMBER:

MDL	0.002 mg/1 0.005 mg/1 0.05 mg/1 0.02 mg/1 0.10 mg/1 0.04 mg/1
RESULT	0.011 mg/1 N/D N/D N/D N/D N/D N/D N/D
ANALYST	JAS KSG KSG KSG KSG KSG
DATE ANAL	12/16/93 12/21/93 12/21/93 12/21/93 12/21/93 12/21/93 12/21/93
ANAL METHOD	EPA 9020 BPA 6010 A BPA 6010 A EPA 6010 A EPA 6010 A EPA 6010 A EPA 7760
PREP METHOD ANAL METHOD DATE ANAL ANALYST	
ANALYTE	TOTAL ORGANIC HALOGEN (TOX) CADMIUM CARCAIUM-FOTAL COPPER LEAD WICKEL SILVER ZINC
SOOD	IA630 IB060 IB090 IB120 IB140 IB190 IB230

* N/D - None Detected





Ross Aluminum Foundries P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

/993 January 5, 1992

Joe E. Sargeant, R.S. Director of Environmental Health SIDNEY-SHELBY COUNTY BOARD OF HEALTH Courthouse Sidney, Ohio 45365

Dear Mr. Sargeant:

Please find attached analysis for spent foundry sand in accordance with your request of January 24, 1990.

Samples were collected by Monte Swank, EID Representative for Brookside Farms Laboratory Assn. and owner of Swank Consulting. Sampling is representative of sand deposited on Ross property west of Brooklyn Avenue located between Fielding Road and Ardiss.

Sincerely,

ROSS ALUMINUM FOUNDRIES

James F. Rinker

Environmental Manager

JFR:cjm

RECEIVED

JAN 0 6 1993

SIDNEY-SHELBY COUNTY HEALTH DEPT

BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448

** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609

Sidney, OH 45345

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker

Lab Number

IE20104

Sample Description

LANDFILL MATERIAL 3 FOUNDRY WASTE

File Number: 60243

Date recv'd: 01/07/92

Date rept'd: 01/20/92

 ~~		

TOXICITY (TCLP Extract	.)	•
Arsenic	mg/	0.002
Barium	mg/!	0.88
Cadmium	mg/	< 0.005
Chromium Lead	mg/!	< 0.05
Mercury.	mg/	< 0.10
Selenium	mg/! mg/l	<.0.00012
Silver	mg/!	0.001
HZO EXTRACT	3 / .	0.03
Cyanides - Totai	mg/	< 0.02
Fluoride	mg/	0.6
Total Phenois	mg/l	< 0.03

BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448

** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45365

File Number: 60243 Date recv'd: 01/14/92 Date rept'd: 01/27/92

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker

Lab Number		UE20105	
Sample Description		LANDFILL H20	
RCRA TESTS TOXICITY (TCLP Extr. Arsenic Barium Cadmium Chromium Chromium Lead Mercury Selenium Silver H2D EXTRACT	mg/ mg/ mg/ mg/ mg/ mg/ mg/ mg/	0.001 6.0 < 0.005 < 0.05 < 0.10 < 0.0002 < 0.00012 < 0.01	
Cyanides - Total Fluoride Total Phenois	mg/ mg/ mg/	< 0.02 1.50 0.23	

Jestrey . Brachok Division Coordinator



Ross Aluminum Foundries P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

January 23, 1992

Joe E. Sargeant, R.S. Director of Environmental Health Sidney-Shelby County Board of Health Courthouse Sidney, Ohio 45365

Dear Mr. Sargeant:

Please find attached analysis for spent foundry sand in accordance with your request of January 24, 1990.

Samples were collected by Monte Swank, EID Rep. for Brookside Farms Laboratory Assn. Sampling is representative of the sand deposited on the ROSS property just west of Brooklyn Avenue and located between Fielding Road and Ardiss.

Should you have questions feel free to contact me.

Sincerely, ROSS ALUMINUM FOUNDRIES

James F. Rinker Environmental Manager

JFR/cjm Environment

BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448

** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45365

File Number: 60243 Date recv'd: 01/07/92 Date rept'd: 01/20/92

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker

Lab Number

IE20104

Sample Description

LANDFILL MATERIAL FOUNDRY WASTE

RCRA TESTS

TOXICITY (TCLP Extract)

Arsenic mg/l Barium mg/l Cadmium mg/| Chromium mg/l Lead mg/l Mercury mg/l Selenium mg/| Silver mg/l

0.88 < 0.005 < 0.05 < 0.10 < 0.00012 0.001 0.03

0.002

H20 EXTRACT

Cyanides - Total mg/l

Fluoride mg/l

Total Phenols mg/l

< 0.02 0.6 < 0.03

Afres P. Brachok Division Coordinator



Ross Aluminum Foundries P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883

RECEIVED

January 15, 1991 W 1 6 91

Joe R. Sargeant, R.S. Director of Environmental Health Sidney-Shelby County Board of Health Courthouse Sidney, Ohio 45365

Dear Mr. Sargeant:

Please find attached analyses for spent foundry sand in accordance with your request of January 24, 1990.

Samples were collected by Monte W. Swank, EID Rep. for Brookside Farms Laboratory Assn. Sampling is of the sand deposited on the ROSS property just west of Brooklyn Avenue and located between Fielding Road and Ardiss.

Should you have any questions, please feel free to call me.

Sincerely,

ROSS ALUMINUM FOUNDRIES

James F. Rinker

Environmental Manager

JFR: cjm



BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448

I.ECENES

** ANALYSIS REPORT **

JAN 1 6 91

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45345

Similar Co. File Number: 60243 Date recv'd: 12/20/9 Date rept'd: 01/04/9

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker

Lab Number

IE08515

Sample Description

12/20/90

LANDFILL WASTE

RCRA TESTS

H20 EXTRACTION

Fluoride

Phenols -

TOXICITY (TCLP Extract) Arsenia

mg/i Barium ms/! Cadmium mg/| Chromium mg/| Copper mg/i Leed Mercury 加多人! Selenium mg/| Silver

ma/l

mg/|

mg/|

0.000a 0.22 < 0.005

< 0.05 < 0.02

< 0.10 < 0.00005 0.0002

< 0.01

< 0.02 0.75

0.04

Total

Cyanides - Total

Coordinator



Ross Aluminum Foundries

P.O. Box 609 Sidney, Ohio 45365-0609 513/492-4134 Fax 513/498-1883



January 30th, 1990

Joe R. Sargeant, R.S. Director Of Environmental Health Sidney-Shelby County Board Of Health Courthouse Sidney, OH 45365

JAN 31 1990

Dear Mr. Sargeant:

Please find attached analyses for spent foundry sand as requested in your letter of January 24, 1990. As you will note, the 1988 data is reported on a "Dry Basis". The 1989 analysis is "Leachate".

ROSS has instructed the testing laboratory to use the leachate procedure on subsequent samplings. A copy of the testing will be forwarded to your office.

To confirm our telephone conversation of January 30, 1990, we are depositing spent foundry sand on ROSS property located west of Brooklyn Avenue, generally between Fielding and Ardiss.

Should you have any questions, please feel free to call.

Sincerely,

ROSS ALUMINUM FOUNDRIES

James F. Rinker

Environmental Manager

JFR/baj

Enclosure

xc: File (2)



DOKELDE FARMS LABORATORY ASSN. INC. nvironmental & Industrial Division New Knoxville: Ohio 45871 (419) 753-2448

JAN 31 1990

** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45365

File Number: 60243 Date recvide 08/28/89 Date reptide 09/08/89

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker

Lab Number

1E94925

Sample Description

RCRA TESTS

TOXICITY (TCLF Extract)

mg/l

mg/|

mg/|

me/kga.

mg/ks

mg/kg

TO ME ! Propose on the Season of the

mg/|

Barium Cadmium Chromium Lead ...

Mercury - Selenium Shlver

- EYANIDES - TOTAL FLUORIDE

TOTAL PHENOLS

(D. Ob.

- 2.5 311

appropriate regulatory agencies.

results presented in this report are laboratory analysis were conducted by mended by the USEPA and/or other and



JAN 31 1990

BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448 ** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45365

EID Rep: Monte W. Swank Attention: Mr. Jim Rinker File Number: 60243
Date recv'd: 08/19/88
Date rept'd: 09/02/88

Lab Number Sample Description 8/18/88

TOTAL SOLIDS	8	98.7
ARSENIC	mg/kg	0.22 *
BARIUM	mg/kg	2.11 *
CADMIUM	mg/kg	< 0.005
CHRONIUM - TOTAL	mg/kg	4 . 66
LEAD	mg/kg	. 3 3 4
MERCURY (Cold Vapor)	mg/kg	< 0.0
PREMOLS - TOTAL	mg/kg	- 6.47
SELENIUM	mg/kg	< 0.000
SILVER	mg/kg	< 0.

Samples are on dry basis.



Peter A. Conidaris Laboratory Manager



JAN 31 1990

BROOKSIDE FARMS LABORATORY ASSN. INC. Environmental & Industrial Division New Knoxville, Ohio 45871 (419) 753-2448 ** ANALYSIS REPORT **

Ross Aluminum Foundries 707-815 N. Oak Avenue P.O.Box 609 Sidney, OH 45365

EID Rep: Monte W. Swank

Attention: Mr. Jim Rinker

Lab	Numbe	r
Samp	le De	scription

TOTAL SOLIDS	8
ARSENIC	mg/kg
BARIUM	mg/kg
CADMIUM	mg/kg
CHROMIUM - TOTAL	mg/kg
LEAD	mg/kg
MERCURY (Cold Vapor)	mg/kg
SELENIUM	mg/kg
SILVER	mg/kg

* Samples are on dry basis.



File Number: 60243 Date recv'd: 08/19/88 Date rept'd: 09/27/88

99.3 0.91

IE83751

Laboratory Manager

0.05 < 0.01



Ohio Environmental Protection Agency

Southwest District Office 40 South Main Street Dayton, Ohio 45402 (513) 449-6357

9 1988 SFP

> Richard F. Celeste Governor

September 6, 1988

SHELBY COUNTY Re:

SOLID WASTE

James R. Rinker Quality Coordinator Ross Aluminum Foundries P.O. Box 609 Sidney, OH 45365-0609

Dear Mr. Rinker:

This letter is in response to your correspondence dated 6/22/88, 8/19/88, and 8/29/88 regarding the proposed exemption of your spent core plaster as a solid waste. To be exempted, the core plaster material must be determined "not harmful or inimical to public health".

The main criteria to determine if the core plaster material is harmful to public health is to ask the question: Can the material pollute the water?

The submitted analysis shows that sulfate and the Alcanol-XC surfactant agent can leach out above the Ohio Drinking Water Standards:

> (OAC 3745-81-11(B)) Ohio Drinking Water

Parameters

Core Plaster Standards (DWS) Test Results

Sulfate 250 gm/l 1,117 mg/1

MBAS .5 mg/l.8 mg/l

Having considered the information submitted regarding the waste, it is a solid waste that must be deposited in a licensed solid waste disposal facility. The core plaster material is not specifically excluded by the definition of solid waste in section 3734.01(E) of the Revised Code and the material can pollute the water.

James F. Rinker Ross Aluminum Foundries September 6, 1988 Page 2

We hope this letter clarifies our position on this matter. Should further questions arise, please do not hesitate to contact us.

Sincerely yours,

loe Moore

M. foe Moore, R.S. Solid Waste Group

MJM/lal

Tom Harcarik, DSHWM/CO Shelby County Transfer Station